

TASK

As for film processing the accurate flow and quantity measurement of photographic solutions is decisive.

SOLUTION

The flow monitor of the series 2101 and a suitable flow sensor of the series 200 or 4000 guarantee for the required accuracy and repeatability. This system provides two computers compatible 2-20mA outputs. The computer controls electro pneumatic control valves and keeps the set flow stable. The flow monitor is also equipped with serial RS 232 output signals.

